



# Blocking an Inspection Lot

- 1. Navigate to: Operations >> Supplier Mgt >> Quality Management>>Change Inspection Lot.




- 2. Input the Inspection Lot Number to be blocked and hit your computer Enter Key.

## Blocking an Inspection Lot



3. The **Change Inspection Lot: Inspection Plan Data** Screen is displayed for the lot number entered.

## Blocking an Inspection Lot



4. At the top left of the screen Click: **Menu >> Inspection Lot >> Functions >> Block Lot**

“System Status” field will now include “LKD”, telling you that the lot has been Blocked / Locked. This allows a new inspection lot to be created for that PO Line item.

-Click the Save button. You can then close the window.